General Environmental Incident Summary

Incident: 3383 Date/Time Notice: 7/14/2014 1428 DEM Incident No:

Responsible Party: Water Works

Date Incident: 6/20/2014 Time Incident: 2200 Duration: 2 minutes

County: Dunn Twp: 146 Rng: 95 Sec: 19 Qtr: SW SW

Lat: 47.45219 Long: -102.83840 Method: Interpolation from map

Location Description: Water Works Salt Water Disposal From Killdeer ND travel north on hwy 22

to mm 119 Water Disposal plant on east side of hwy

Submitted By: Ken McGuire Affiliation:

Address: 828 Hwy 22N

City: Killdeer State: ND Zip:

Received By:

Contact Person: Ken McGuire

828 Hwy 22N

Killdeer, ND 58640

Distance Nearest Occupied Building: 2000 Feet Release Contained: Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Crude Oil & Produced Salt Water

Volume Spilled: 6.00 barrels Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Truck drive was not paying attention and overflowed frac tank

Risk Evaluation:

none

of Fatalities: # of Injuries: Affected Medium: 03 - soil

Potential Environmental Impacts:

soil has oil and salt water residue

Action Taken or Planned:

Sucked water and oil from ground Will be having Bear Mountain LLC (701-627-2494) clean up affected soil and haul to solids disposal on 7/15/2014 starting clean up at 9:00 am

Wastes Disposal Location: Oil and water were injected into our disposal well, contaminated soil will

be disposed of at solids waste disposal

Agencies Involved:

Updates

Date: 7/14/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Volume:

Notes:

Release, within containment, remained on location according to the report. NDIC retains oversight. Report forwarded to NDIC.